





ASSEMBLY INSTRUCTION FOR GLENVIEW 6 DRAWER DRESSER

A		Tipping Hardware	1 PC
B		Screwdrivers (Not included)	1 PC







Tipping Hardware

