







ASSEMBLY INSTRUCTION

MODEL: Lewis Swivel Stool Bar

HARDWARE LIST				
A		Washer	6-16	4
B		Spring washer	6-10	4
C		Bolt	6-20	4
D		Allen key	M4	1



Step: 1

