





ASSEMBLY INSTRUCTION FOR  
GRAND CABINET


| HARDWARE LIST |                                                                                   |                                |            |       |
|---------------|-----------------------------------------------------------------------------------|--------------------------------|------------|-------|
| A             |  | Bolt                           | M6 x 20 mm | 8     |
| B             |  | Washer                         | 6 x 13mm   | 8     |
| C             |  | Lock Washer                    | 46 x 60 mm | 2     |
| D             |  | Allen Key                      | 4mm        | 1     |
| E             |  | Tipping Hardware               |            | 2 SET |
| F             |  | Screwdrivers<br>(Not included) |            | 1     |





# COMPONENTS




1




2




3





Tipping Hardware



Tipping Hardware

