


ASSEMBLY INSTRUCTION

Ludvig Desk Chair

Components




a
x1



b
x1




C
x1


$$\frac{d}{dx_1}$$




e
x5

Step 1



Step 2

Hardware List				
f		Bolt	M8×30	4
g		Flat Washer	16×8	4
h		Spring Washer	M8	4
i		Allen key		1



Made in China